

INSPECTION REPORT REVIEW
POTENTIAL HAZARDOUS WASTE SITE

SITE NAME : CJ Martin Co

LOCATION : Nacogdoches

SITE NUMBER: TXD008144388

SURVEY DATE: 1-1-94 INSPECTED BY: STATE FIT TAT OTHER: ECOLY EAV ^{SIP Report}

LABORATORY : CLP EPA OTHER

RECEIVED FROM: Betty Williamson DATE RECEIVED: 9/17/94

SAMPLE TYPE(s): NONE

SOIL	SURFACE WATER	GROUND WATER	DRINKING WATER
off / on -site	off / on -site	off / on -site	off / on -site

CONTAMINANT(s): Organics Inorganics Radionuclides Microbiological

FOLLOW UP (Y/N):

<u>N</u> (Re)Sampling Requested	<u>N</u> Locate Drinking Water Sources
<u>N</u> Further Action is URGENT	<u>N</u> Keep Site Active ("N"=No Further Action)
	<u>N</u> Concur with Report Recommendations

SUMMARY: This is review of an SIP report for an active insecticide formulator. Soil boring do not indicate on-site contamination. Lindane was detected in sediment and surface water sample collected in an off-site drainage ditch.

Ground water is used for drinking water within target distance including a 500 feet deep private well within one mile of the site.

Concur with referral to the TNRCC for possible assessment.

RECOMMENDATION: None

Concurrence:

Neil R. Plam

12/29/94

Neil R. Plam
ENGINEER/REVIEWER

12/29/94

EDG 12/8